



Ford Motor Company  
P.O. Box 1904  
Dearborn, Michigan 48121-1904  
[www.ownerconnection.com](http://www.ownerconnection.com)

2000

Vehicle ID #: 1F *File Copy*

01S24

October, 2001

STATE OF UTAH  
FLEET OPERATIONS MOTOR  
P O BOX 141117  
SALT LAKE CITY, UT 84114

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 2000 and 2001 model year cars and trucks.

**What the safety issue is ...**

In some of the affected vehicles the wiper motor park switch (located in the wiper motor) may malfunction and cause one of the following conditions:

- Loss of wiper intermittent park function (low and high speeds still operate)
- Complete loss of all wiper function
- Complete or partial loss of wiper function, and the melting of the plastic wiper motor cover, potentially resulting in smoke and/or localized fire.

**What Ford Motor Company and your dealer will do ...**

Ford Motor Company will repair your vehicle free of charge (parts and labor). Owners who are affected by this recall are requested to return their vehicle to their dealer for replacement of the wiper motor cover assembly, if inspection of the wiper motor build date code determines that it was built within the suspect period.

**How long will it take?**

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.